31502,31503

Xerox® AltaLink® C8230/C8235/C8245/C8255/C8270
Color Multifunction Printer

# Repeating Defects

To identify the component causing the defect, compare your print sample against the measurements shown.

To diagnose a defect on the transfer belt:

1. Print eight Letter/A4-size pages long-edge feed. Verify that the same defect appears on every fourth page.

Or

2. Print four Tabloid/A3-size pages. Verify that the same defect appears on every other page.

Call for service for this defect.

| Drum Cartridge | | Second Bias Transfer Roll | Fuser Pressure Roll (Service only) | Fuser Heat Belt (Service only) | Developer Roller (Service only) |
|---|---|---|---|---|---|
| 95 mm (3.74 in.) | 38 mm (1.50 in.) | 65 mm (2.55 in.) | 88 mm (3.40 in.) | 96 mm (3.78 in.) | 33 mm (1.29 in.) |