Repeating Defects



To identify the component causing the defect, compare your print sample against the measurements shown.

To diagnose a defect on the transfer belt, print eight Letter/A4-size pages. Verify that the same defect appears on every fourth page.

Call for service for this defect.

Imaging Unit

- 43.6 mm (1.72 in.)
- 45 mm (1.77 in.)
- 94.5 mm (3.72 in.)
- 29.9 mm (1.18 in.)
- 23.2 mm (.91 in.)

Transfer Unit

- 37.7 mm (1.48 in.)
- 78.5 mm (3.09 in.)
- 54.6 mm (2.15 in.)

Fuser

- 95 mm (3.74 in.)
- 110 mm (4.33 in.)

© 2023 Xerox Corporation. All Rights Reserved. Xerox® and VersaLink® are trademarks of Xerox Corporation in the United States and/or other countries. BR38409