Repeating Defects



To identify the component causing the defect, compare your print sample against the measurements shown.

To diagnose a defect on the transfer belt, print eight Letter/A4-size pages. Verify that the same defect appears on every fourth page.

Call for service for this defect.

Imaging Unit: 43.6 mm (1.72 in.), 45 mm (1.77 in.), 94.5 mm (3.72 in.), 29.9 mm (1.18 in.), 23.2 mm (.91 in.)

Transfer Unit: 37.7 mm (1.48 in.), 78.5 mm (3.09 in.), 55 mm (2.17 in.), 28.3 mm (1.11 in.)

Fuser: 79.8 mm (3.14 in.), 94.3 mm (3.71 in.)

© 2022 Xerox Corporation. All Rights Reserved. Xerox® and VersaLink® are trademarks of Xerox Corporation in the United States and/or other countries. BR34463