



37598 / 3759L

Repeating Defects



Imaging Unit




To identify the component causing the defect, compare your print sample against the measurements shown.

To diagnose a defect on the transfer belt, print eight Letter/A4-size pages. Verify that the same defect appears on every fourth page.

Call for service for this defect.



Transfer Roller



Fuser

