

Xerox® VersaLink® B625 MFP Security Lockdown Confirmation Report

xerox™

Security Settings are compliant.

ACTION: Not Set.

Report Details:

Submission Date: 08/02/24
Submission Time: 05:47 PM
Device Information:

Device Status: Lockdown SUCCESS
Details:

Device Name: Xerox VersaLink B625 MFP (AC:17:78)
Location: machine location not set
Serial Number: 5321605321
Customer Asset Tag:
Xerox Asset Tag:
Host Name: XRX788C77AC1778.XEROXQA.COM.
MAC Address: 78:8C:77:AC:17:78
IP Address: 10.61.16.24

Xerox® VersaLink® B625 MFP Security Remediation Confirmation Report

xerox™

Remediation Successful. Security Settings are now compliant.

ACTION: Not Set.

Report Details:

Submission Date: 08/02/24
Submission Time: 05:46 PM

Device Status: Remediation SUCCESS

Details: Settings Remediated
Print From USB
Scan To USB
Scheduled Job Data Removal

Device Information:

Device Name: Xerox VersaLink B625 MFP (AC:17:78)
Location: machine location not set
Serial Number: 5321605321
Customer Asset Tag:
Xerox Asset Tag:
Host Name: XRX788C77AC1778.XEROXQA.COM.
MAC Address: 78:8C:77:AC:17:78
IP Address: 10.61.16.24